

TECHNICAL SHEET

Basel - jacket

description

• 2 lower pockets • 2 breast pockets • 1 left arm little pocket • adjustable waist • adjustable cuffs • stretch fabric • good resistance to abrasion • good resistance to washings



maintenance

maximum wash temperature: 40 $^{\circ}\text{C}$ - do not bleach – do not dry cleaning - drying in tumble dryer not allowed - medium iron temperature: 110 ℃













item	V150-0-00 blue jeans/copper seams			
standards				
sizes	44 – 64			

SAFETY TECHNICAL SPECIFICATIONS

	Test method	description	Cofra result	minimum requirement / range
Background fabric	EN ISO 1833-1977, SECTION 10	Composition:	Cotton 70%,	
			Polyester 27%,	
			Elastane 3%	
	EN ISO 12127:1996	Weight per unit area	330 g/sqm	

Version 2.0